

FILE CODE Gamma Survey

DATE 7-19-85

NAME _____

PHONE _____

ADDRESS 3858 GARNET DR.

TYPE OF REQUEST

Request from potential IMPERIAL LAKES, - LKLD.
home buyer to take & survey of property.

CONDITIONS FOUND AND ACTION TAKEN

Stopped by house (address above) while
in Lkld. area. Performed & survey. (See below)
LUDLUM SN. 7152. (CORRECTED VALUES BELOW)
(WHITE & GRAY BRICK HOUSE)

Gamma Survey on back of card. →

INVESTIGATED BY

DATE

Tom McNally 7-19-85
RAD/9 Radiological Health Investigation and Complaint Card

REDACTED

SITE: Florida Phosphate
BREAK: 17.8
OTHER: v. 45



10518254

DATE	REMARKS ON FOLLOW-UP VISITS	INITIAL
	<div style="border: 1px solid black; padding: 10px; width: fit-content; margin: 0 auto;"> 3858 GARNET DR. </div>	
	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> 8 8 7 </div> <div style="text-align: center;"> 8 7 </div> <div style="text-align: center;"> 5 5 5 </div> </div>	

FILE CODE

DATE 5/18/79

NAME

Melodie

McFadden

PHONE

(b) (6)

ADDRESS

(b) (6)

TYPE OF REQUEST

Property surveyed FOR RADIATION - Forest Green S/O -

Greenwood St., Lakeland -


(b) (6)

CONDITIONS FOUND AND ACTION TAKEN

Phoned 5-18-79 - Letter to be sent NMG

& Survey Performed Wall & Gilley - BACKGROUND

INVESTIGATED BY



DATE

30 May 79

RAD/9 Radiological Health Investigation and Complaint Card

FILE CODE RAD - Gamma Survey

DATE 21 Sep 83 (b) (6)

NAME Wm. Cardman

PHONE _____

ADDRESS (b) (6)

TYPE OF REQUEST Phone Request - Survey & Explanation of Indoor Radon Problems of Reclaimed lands. Meeting 3:00p at Building Site 22 Sep 83

CONDITIONS FOUND AND ACTION TAKEN Gamma Survey - Highest level ~15 mR/hr

- Meeting with Dr Cardman on site for House layout
- will have "clean" fill ~1 ft deep
- SAND clay mixture - PIT side
- LOT staked out with house also staked for footer
- Parts of lot had standing H₂O

INVESTIGATED BY NMG/16 DATE 9-23-83

RAD/9 Radiological Health Investigation and Complaint Card

A hand-drawn sketch of a building corner. The corner is formed by two vertical lines and a horizontal line at the top. The word "CEDAR" is written horizontally across the middle of the sketch. There are some scribbles and lines at the bottom of the sketch.

- CEDAR SIDING

GOLDEN ROD
COURT

SITE PLAN



DEPARTMENT OF HEALTH AND REHABILITATIVE SERVICES STATE OF FLORIDA

Reubin O'D Askew, Governor

File Reports

DISTRICT EIGHT POLK COUNTY HEALTH DEPARTMENT

WILLIAM F. HILL, JR., M.D.
DIRECTOR

P.O. BOX 1480
229 AVENUE D, N.W.
WINTER HAVEN, FLORIDA
33880

DIRECT SERVICE UNITS

1755 HOLLAND PKWY., SOUTH
BARTOW, FLORIDA 33830

111 NORTH 11TH STREET
HAINES CITY, FLORIDA 33844

305 WEST CENTRAL AVENUE
LAKE WALES, FLORIDA 33853

103 EAST CANAL STREET
MULBERRY, FLORIDA 33860

DIRECT SERVICE UNITS

1333 NORTH FLORIDA AVENUE
LAKELAND, FLORIDA 33801

P.O. BOX 33
WAVERLY, FLORIDA 33877

2 NORTH REEDY BLVD.
FROSTPROOF, FLORIDA 33843

243 E. LAKE AVENUE
AUBURNDALE, FLORIDA 33823

8 June 1977

Myrtle Hill Real Estate
3822 South Florida Ave.
Lakeland, FL 33803

RE: 3622 Grove Terrace.

Dear Gentlemen:

This office performed a radiation survey on the property located in Lakeland at 3622 Grove Terrace, as requested by a representative of your office.

We performed this gamma survey around the outside of the home and encountered readings of 2 to 4 microRoentgens per hour. These readings are well below the interim standard of 10 microRoentgens per hour recommended by the Environmental Protection Agency for the construction of new structures on reclaimed phosphate lands.

Sincerely,

Keith B. Moore
Industrial Hygienist

KBM/nmg

INDOOR RADON SCREENING FORM

3-78 → 0.019,
5-78 - 0.019
1-2778 - 0.022

Location File

Location No.

7	1	4	0	5
1	2	3	4	5

City

6	7	8	9

County

11	12	13

State

15	16

Address

Number

	(b) (6)
18	19

Street

(b) (6)
24

Occupant

Code

A

C	A	R	R	E	I	R	A										
40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57

Data File (CARD A)

Location No.

7	1	4	0	5
1	2	3	4	5

GF
Gamma

7	8	9

Outdoor Gamma

11	12	13

Classification

1
27

Type Structure

2
29

No. of Levels

1
31

Material

1
33

Air
Conditioning

1
35

- 0. Vacant Lot
- 1. Residence single family
- 2. Multiple (4 families)
- 3. Apartment (>4)
- 4. Motel, hotel
- 5. Single business
- 6. Multiple business
- 7. School
- 8. Church
- 9. Other

- 1. Basement
- 2. Slab on grade
- 3. Crawlspace
- 4. Trailer
- 5. Unknown

- 1. Masonry
- 2. Non-masonry

- 1. Yes
- 2. No

Central
Air + Heat
(always
closed up)

Date


Yr Mo Day

7	8	0	1	2	7
37	38	39	40	41	42

Card Code

O	R	I	G
77	78	79	80

PCHD Ludlum # 7152



FILE CODE Gamma Survey

DATE 12/19/85

NAME DR CHATMAN

PHONE

(b) (6)

TYPE OF REQUEST _____

Request of Survey of Home

CONDITIONS FOUND AND ACTION TAKEN Survey Performed - Background
LEVELS FOUND - Letter sent to
Realtor (PAT BLALOCK).

INVESTIGATED BY Tom McDally DATE 12/19/85
RAD/9 Radiological Health Investigation and Complaint Card


DATE

REMARKS ON FOLLOW-UP VISITS

INITIAL

LUDLUM # 4633

OUTSIDE



A MEMBER OF THE SEARS FINANCIAL NETWORK

**COLDWELL
BANKER**

**FOX & SAVAGE
REALTY, INC.,**
REALTORS®

3240 S. FLORIDA AVE.
LAKE LAND, FL 33803
BUS. (813) 646-5056
RES. (813) 682-6512



PATRICIA C. BLALOCK
REALTOR®-ASSOCIATE



An Independently Owned and Operated Member of Coldwell Banker Residential Affiliates, Inc.



3240 S. FLORIDA AVE.
LAKELAND, FL 33803
BUS. (813) 646-5056

DECEMBER 18, 1985

FOX & SAVAGE
REALTY, INC.,
REALTORS*

MR. NORMAN M. GILLEY
RADIOLOGICAL HEALTH
ENVIRONMENTAL ENGINEERING DIVISION
POLK COUNTY HEALTH DEPARTMENT
Box 1480
WINTER HAVEN, FLORIDA 33880

DEAR MR. GILLEY:

AS WE DISCUSSED THIS MORNING, IT IS NECESSARY THAT I HAVE PROOF
THAT A RESIDENTIAL AREA HERE IN LAKELAND HAS NEVER BEEN MINED
FOR PHOSPHATE PURPOSES.

THE AREA IS GLENMORE WHICH IS IN THE SOUTHEAST SECTION OF LAKELAND.
DIRECTIONS: OFF LAKE MIRIAM DRIVE, GO SOUTH ON LUCE ROAD TO
GLENMORE.

A SALES CONTRACT IS CONTINGENT UPON PROVING THAT THIS AREA HAS NEVER
BEEN MINED. MAY I PLEASE HAVE A RESPONSE AS SOON AS POSSIBLE?


PLEASE SEND INFORMATION TO:

PAT BLALOCK
FOX & SAVAGE REALTY, INC.
3240 SOUTH FLORIDA AVENUE
LAKELAND, FLORIDA 33803

SINCERELY,

A handwritten signature in cursive script that reads "Pat Blalock".

PAT BLALOCK
REALTOR-ASSOCIATE



DISTRICT SIX
POLK COUNTY PUBLIC HEALTH UNIT

DIRECT SERVICE UNITS

1755 HOLLAND PKWY SOUTH
BARTOW, FLORIDA 33830111 NORTH 11TH STREET
HAINES CITY, FLORIDA 33844G.A. REICH, M.D. M.P.H.
DIRECTOR229 AVENUE D N.W.
P.O. BOX 1480
WINTER HAVEN, FLORIDA
33882-1480

DIRECT SERVICE UNITS

1333 NORTH FLORIDA AVENUE
LAKELAND, FLORIDA 33805305 WEST CENTRAL AVENUE
LAKE WALES, FLORIDA 33853

Patricia C. Blalock
Fox and Savage Realty, Inc.
3240 S. Florida Ave.
Lakeland, Fla. 33803

Dear Mrs. Blalock,

As per your request, this letter is in reference to the gamma survey performed at 5463 Glenmore Rd., Lakeland, Fla. on Dec. 19, 1985. As I explained to you at that time, the gamma levels on the lot surrounding the house and the gamma levels inside the house were between 4 and 7 micro-Roentgens per hour (uR/hr). These are normal background levels for Florida and are common for non-reclaimed and non-mineralized land.

Proposed HRS regulations would set a gamma limit of 20 uR/hr inside the home and a radon daughter limit of .02 Working Levels (WL). Since the gamma level at this site is so low, there is no need for any further testing for radon daughter level.

If I can be of any further assistance, please do not hesitate to call.

Sincerely,

Tom McNally

FILE CODE GAMMA SURVEY

DATE 8-28-85

(b) (6)

NAME Keith Alexander

PHONE (b) (6)

TYPE OF REQUEST Wants gamma survey on lot #387

Phase 9

On Hayton Rd. across from entrance to Goldenrod Ct.

CONDITIONS FOUND AND ACTION TAKEN Performed gamma survey on 8-28-85
Results on attached sheet

INVESTIGATED BY Tan McNally DATE 8-28-85
RAD/9 Radiological Health Investigation and Complaint Card

912 Heather Crest

Radiological & Occupational Health
107 North Church Street
Mulberry, Florida 33860
May 9, 1977

Ms. Goldie DeBoy, Realtor
Wanda Wilson Realty, Inc.
2001 Bartow Hwy.
Lakeland, Florida 33801

Dear Ms. DeBoy:

Please find the enclosed report on the residence at 912 Heather Crest Lane, Lakeland, Florida.

In the future this office will perform such surveys and will report the finding as you request them. These requests must be in written form, outlining the locations to be surveyed and proper permission release from the current owner for such surveys.

This office will be most happy to assist you with these problems as they arise.

Sincerely,



Norman Michael Gilley
Industrial Hygienist

NMG/bb
enclosure

Radiological & Occupational Health
107 North Church Street
Mulberry, Florida 33860
May 9, 1977

Dr. Richard L. Rutherford

(b) (6)


Dr. Rutherford:

Please find the enclosed report of the gamma survey performed at (b) (6) as requested of this office by Wanda Wilson Realty, Incorporated; and, the "Florida Phosphate Lands, Interim Recommendations for Radiation Levels" from the Federal Register, Volume 4, No. 123, Thursday, June 24, 1976.

After reviewing both, please note that the readings taken at the Heather Crest home were below the 10 uR/hr (micro Roentgen per hour) level used as a guideline for the current EPA/Florida Radiological impact study. Also be advised that this home lies on what appears to be land adjacent to reclaimed ponds and not necessarily on reclaimed land.

Please contact this office if any questions arise or if we can be of further assistance.

Sincerely,



Norman Michael Gilley
Industrial Hygienist

NMG/bb

POLK COUNTY HEALTH DEPARTMENT

FIELD REPORT ON 912 Heathercrest Ln.
 TOWN VISITED Lakeland, FL DATE 9 MAY 1977
 OWNER OF PROPERTY Wanda Wilson Realty PERSON SEEN Ms Goldie DeBoy
 BY WHOM Norman Michael Gilley TIME SPENT 1 hour +
 REASON FOR VISIT Requested gamma survey

REPORT:



SAN 17 All Readings Noted ARE in micro-ROENTGENS PER HOUR, AS PER Ludlum 12S serial #5271

FILE CODE RAD Gamma Survey

DATE 21 AUG 80 (b) (6)

NAME Mr O.J. Kyshto (b) (6)

ADDRESS (b) (6)

TYPE OF REQUEST Gamma Survey

CONDITIONS FOUND AND ACTION TAKEN

Survey performed 21 AUG 80

WTM = valley - Ludden walk over

Letter - NMG 27 AUG 80

INVESTIGATED BY

DATE

RAD/9 Radiological Health Investigation and Complaint Card

August 27, 1980

Mr. O. J. Kushto

(b) (6)

Dear Mr. Kushto:

As requested, a member of this office performed a walk over gamma survey of the Saddle Creek property denoted by the plat supplied to this office.

Please be advised that the radiation levels measured (mean exposure 7micro R/hr) did not exceed the 10 micro Roentgen per hour level denoted by the Surgeon General. This 10 uR/hr level was selected as studies indicate that above it, potential health hazards could exist.

Thank you for your interest in Radiological Health. Please contact this office if we may be of further assistance.

Sincerely yours,

Norman M. Gilley
Public Health Physicist

POLK COUNTY HEALTH DEPARTMENT

FIELD REPORT ON O. J. KUSATO PROPERTY (Gamma Survey)
TOWN VISITED LAKELAND - SADDLECREEK DATE 8-21-80
OWNER OF PROPERTY (b) (6) PERSON SEEN —
BY WHOM Tom McNally TIME SPENT 2 hrs.
REASON FOR VISIT Gamma Survey

REPORT: Gamma Survey requested by O. J. Kusato.
114 readings recorded on property.

Average reading was 7.29
Highest was 16.
Lowest was 5.


Unable to survey some parts due to thick brush.

Property located just West of Saddle Creek Park
and directly North of small bridge.

O.J.Kushto

~~XXXXXXXXXXXX~~

(b) (6)



TO Polk County Health Dept.
P.O.Box 1480
Winter Haven, Fla. 33880

DATE 8-14-80

SUBJECT Survey


Attention Mr. Gilley

Sir;

I would like to request a radiological survey be made on the property located at 3600 U.S. 92 East, Lakeland, Fla. which is just west of Saddle creek park.....See enclosed plot plan.....

Many Thanks

I can be reached at above phone number.....



Survey 4-22-78

COVER ENGINEERING, INC.

BY CERTIFY: That the plat shown hereon
above described property is true and
to the best of my knowledge and belief
was made under my direction.

By:

W. E. Cover, PLB #1521

Highway 18 South

Hauger-Bunch

REALTORS

February 21, 1978

Polk County Health Department
Radiological Health Services Division
Avenue D
Winter Haven, Florida 33880


ATTENTION: Mr. Keaton

Dear Mr. Keaton:

Your department has permission to enter onto the property described in Addendum I hereto for the purpose of making radiological measurements.

Very sincerely,

HAUGER-BUNCH, INC.



David F. Bunch
REALTOR
Agent for Owners

DFB/let

Attachments: Addendums I, II, & III

IDENTIFICATION AND LEGAL DESCRIPTION

The property being tested contains 136 acres of land. It is located on the east side of U. S. Highway 98 and the Seaboard Coast Line Railroad. The site is popularly referred to as "Vo-Tech Site" because of its location immediately south and adjacent to the Polk County Vocational Center. The property is legally described as follows:

The NW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Section 2, Township 29 South, Range 24 East, containing approximately 40.5 acres.

AND

That part of the NE $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Section 3, Township 29 South, Range 24 East, lying East of the Seaboard Coast Line Railroad, and containing 14.2 acres, more or less.

AND

That part of the SW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Section 2, Township 29 South, Range 24 East, lying North of the centerline of Banana Creek and East of Seaboard Coast Line Railroad right-of-way, and containing approximately 2 acres.


AND


That part of the SE $\frac{1}{4}$ of the SE $\frac{1}{4}$ of Section 3, Township 29 South, Range 24 East, lying North of Banana Canal and East of Seaboard Coast Line Railroad right-of-way, containing approximately .25 acre.

AND

The S $\frac{1}{2}$ of the NW $\frac{1}{4}$ of Section 2, Township 29 South, Range 24 East, containing approximately 80 acres.

ADDENDUM II



An aerial photograph of a rural landscape. A road runs diagonally from the top left towards the bottom right. To the right of the road, there is a large, rectangular building with a dark roof. The surrounding area is a mix of fields and some smaller structures. The image is in black and white with a grainy texture.

Polk Vo-Tech
Center

ADDENDUM III

Radiological And Occupational Health
Post Office Box 1480
Winter Haven, Florida 33880

February 24, 1978

David F. Bunch

(b) (6)

Dear Mr. Bunch:

On 2/21/78 this office performed a limited Radiation Survey Covering the area shown in the attached Addendum II. Two types of tests were performed (1) a general gamma survey performed with 2 Iudlum model 12 S Micro R meters, serial numbers 7152 and 7059 the results of which were no gamma readings exceeded 7 microroentgen per hour and all readings in the test area ranged from 5 to 7 micro/R per hour. This is about average background for the State of Florida. (2) The second test was the measurement of radon flux emanating from the various numbered locations on Addendum II. The readings from each of these locations were combined to give an average radon emanation rate for the tested area. The average flux for this area was 123.3 atto Curies per centimeter square per second, which is about 2.5 times the National Average.

From the above data (1) at or near background gamma radiation levels. (2) Low average radon emanation rate, and also considering the owners intended usage of the land for college type school construction in which occupancy will be only for minor portions of the day.

I can see no complications from a Radiological Health Standpoint for the above type construction!

Sincerely,

Harlan Keaton
Industrial Hygienist

S R 540 -A

Reynolds Road

Required Reynolds Road Extension

Polk Vocational Technical Center

Retained by Pickard

2640'

1320'

810'

11910'

TEST AREA

SUBJECT 136 ACRE

Pickard portion)

Roberts portion)

Low Area

Banana Creek

City Owned

U. S. 98 South

SCL RR

BELLATON

DATE Feb. 24, 1978

RADON FLUX DATA SHEET

SYSTEM EFF: 0.221 CPM/PCIPolk County Health Department
Radiological Health SectionDeployed by Keaton & Gilley 2/21/78
Retrieved by Gilley & Nail 2/24/78Analyzed by N.M. Gilley

Retrieved by Gilley & Hall 2/24/78

SAMPLE LOCATION	CANISTER NUMBER	DATE - TIME			NET CPM	$\text{Ci cm}^{-2} \text{sec}^{-1}$ ^{222}Rn FLUX	REMARKS
		START 2/21	STOP 2/24	READ 2/24			
Proposed	60	1410	845	1400	182.2	52.90	
Building Site	8	1412	Lost				
of Polk Tech.	158	1415	850	1430	53.4	15.55	
Hauger-Bunch	214	1420	851	1410	110.7	32.18	
SR.540 At 98N	144	1423	853	1514	86.4	22.63	
Lakeland	48	1425	855	1502	172.4	50.44	
	26	1428	858	1538	209.0	60.39	
	151	1430	859	1034	476.5	138.24	
	3	1433	901	1526	122.8	36.02	
	157	1435	903	1380	107.8	31.15	
	52	1438	905	1553	76.4	22.48	
	17	1440	909	1508	208.8	61.03	
	6	1441	910	1420	372.8	108.30	
	111	1443	912	1533	109.8	32.18	
	161	1445	915	1440	105.1	30.58	
	183	1450	916	1045	128.9	36.44	
	131	1452	918	1143	99.6	26.93	
	164	1455	920	1013	453.6	127.67	
	146	1456	922	1023	1904.4	536.47	
	139	1458	924	1451	241.4	70.3	
	129	1500	926	1122	296.2	84.02	
	222	1501	927	1108	266.7	75.51	

COMMENTS:

$$X = 123.30 \text{ atto Curies cm}^{-2} \text{sec}^{-1}$$

Standard Deviation

DATE _____
SYSTEM EFF:0.

CPM/PCI

RADON FLUX DATA SHEET


**Polk County Health Department
Radiological Health Section**

Deployed by Keaton/Gilley 2/21/78
Retrieved by Nall & Gilley

Analyzed by N.M. Gilley

[illegible]


COMMENTS :



1811 Crystal Lake Dr
(HANGED BUNCH)

DAVID BUNCH

(b) (6)



FILE CODE RAD HEALTH

DATE 12 OCT 79

NAME MR George C Miller

PHONE (b) (6)

TYPE OF REQUEST "TEST Home for Radiation"

CONDITIONS FOUND AND ACTION TAKEN

Gamma Survey revealed 506 mR/hr
exposures outside as well as inside

Also time spent on discussion of radiation/reclaimed loads
& their residence

INVESTIGATED BY [Signature]

DATE 12 OCT 79

RAD/9 Radiological Health Investigation and Complaint Card

9:30

POLK COUNTY HEALTH DEPT.
RADIOLOGICAL HEALTH
P.O. Box 1480
WINTER HAVEN, FL. 33880
ATT: MR. HARLAN KENTON;

DEAR SIR:

PURSUANT TO OUR PHONE CON-
VERSATION THIS DATE, WOULD LIKE
TO HAVE OUR HOME TESTED FOR
RADIATION.

I SINCERELY BELIEVE ALL THE
HOMES IN THIS COMPLEX WERE
BUILT ON MINDS OUT LAND.

THERE IS STILL A HILL OF
OUR BURDEN LESS THAN 100 FT. BE-
HIND OUR HOME.

TRUSTING THIS WILL RECEIVE
THE PROPER ATTENTION.

I AM, YOURS VERY TRULY,

G. C. Miller

(b) (6)

G. C. MILLER

IMPERIAL SOUTHEAST VILLA #210,
LAKE LAND, FL. 33801

8

7

8

K

7

D

L 8

8

STORAGE

N ↙

HALL

8

BR

8 BA

CAR
PORT

8

8

street

Ludlow 12/8
7152

INDOOR RADON SCREENING FORM

Location File

Location No.

--	--	--	--	--

1 2 3 4 5

City

L	K	L	D
---	---	---	---

6 7 8 9

County

--	--	--

11 12 13

State

F	I
---	---

15 16

10-12-79

Address

Number

	(b) (6)				
--	---------	--	--	--	--

18 19 20 21 22

Street

(b) (6)																				
---------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

24 25 26 27 28 29 30 31 32 33 34 35 36 37 38

Occupant

Code

A

M	i	L	L	E	R	,	G	E	O	R	G	E		C			
---	---	---	---	---	---	---	---	---	---	---	---	---	--	---	--	--	--

40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57

Data File (CARD A)

Location No.

--	--	--	--	--

1 2 3 4 5

GF
Gamma

--	--	--

7 8 9

Outdoor Gamma

--	--	--

11 12 13

Classification

1

27

Type Structure

2

29

No. of Levels

1

31

Material

1

33

Air
Conditioning

1

35

0. Vacant Lot *duplex sharing car ports*
1. Residence single family
2. Multiple (4 families)
3. Apartment (>4)
4. Motel, hotel
5. Single business
6. Multiple business
7. School
8. Church
9. Other

1. Basement
2. Slab on grade
3. Crawlspace
4. Trailer
5. Unknown

1. Masonry
2. Non-masonry

1. Yes
2. No

Date

Yr Mo Day

7	9	1	0	7	9
---	---	---	---	---	---

37 38 39 40 41 42

Card Code


O	R	I	G
---	---	---	---

77 78 79 80

POLK COUNTY HEALTH DEPARTMENT

FIELD REPORT ON Gallen Villa #75 Imperial Southgate
TOWN VISITED Wald DATE 12/20/77
OWNER OF PROPERTY _____ PERSON SEEN Mrs. Gallen
BY WHOM W. Hall TIME SPENT 20 min.
REASON FOR VISIT Gamma survey

REPORT:



POLK COUNTY HEALTH DEPARTMENT


FIELD REPORT ON Vacant Lot (Iowa Ave.
 TOWN VISITED Eaton Park Fl DATE 6/30/78 and 7/5/78

OWNER OF PROPERTY (b) (6) PERSON SEEN (b) (6)

BY WHOM W. Nall TIME SPENT

REASON FOR VISIT Deployment & retrieval of flux cans. Gamma survey

REPORT:



black - cannister #1's
 red - gamma (MR/hr.) - PCHD Ludlum # 7152

RADON FLUX DATA SHEET

Polk County Health Department
Radiological Health Section


Deployed by W. Wall
Retrieved by W. Wall

Analyzed by NMGilley

[illegible]

COMMENTS :

$$\bar{X} = 20.39 \pm 14.60 \text{ atto Ci} \cdot \text{cm}^{-2} \cdot \text{sec}^{-1}$$



Dear Mr Keaton

I am writing, Ref a request
to have my Valent lot on (b) (6)
(b) (6) tested for radiation. The lot is
located on (b) (6), on what is
believed to be an old phosphate pit.
The little body of water has been
there so long for any living person
to remember. To reach this lot, (b) (6)

(b) (6)

(b) (6) You will have to call me a day
ahead of time, as I work irregular hours,
& I will meet you & unlock the gate for you.
I am most anxious to complete this
test as soon as possible & thank you
very much for your time & cooperation

Sincerely, Ruby Cootey

(b) (6)

P.S. There is no street # on the fenced lot
only a water tap, & several trees that
I recently had set.

Radiological And Occupational Health
Post Office Box 1480
Winter Haven, Florida 33880

July 7, 1978

Ruby Cawley

(b) (6)

Dear Mrs. Cawley:

The results obtained from the deployment of eight radon flux
cannisters on your lot located on Iowa Avenue in Eaton Park,
Florida, showed an average radon flux of 20.4 aCi/cm² sec.

This is well below the interim standard set by the Environmental
Protection Agency of 50 aCi/cm² sec., for normal construction
practices in building a new home.

If we can be of any further help to you, feel free to contact us.

Sincerely,

Wesley Nall
Industrial Hygienist I

WN/rch